

Torque Sensor

Rotating Torque Sensor

Type 4501A...

Type 4501A... torque sensors operate on the strain gage principle and supplies an analog output signal in mV/V. The sensors are particularly suitable for screw driving assembly operations.

- Universal applications
- Strain gage full bridge system
- Shunt calibration
- Measurement of torque in either direction of rotation
- Short term speed peaks to 3 000 1/min
- Robust and reliable design
- Small and handy
- Long service life
- Resistant to high acceleration
- Optional rotational angle measurement

Description

These sensors use strain gage technology. Power is supplied and the measurement signal transferred between the rotating shaft and the case via high-grade, durable slip rings. These torque sensors are predominantly employed as in-line torque sensors. They are robust and easy to use.

Together with a broad range of measuring and evaluation systems they are ideal instruments for precise and low-priced measurement of torque and torque angles.

Application

The Type 4501A... torque sensors were designed specifically for use in screw driving assembly applications. The versions with square or hexagonal shaft mount directly on the drives of the tools.

Typical applications include checking stationary screw spindles and torque measurement hand or power driven.

The universal versions with rounded shaft ends can be used wherever torque has to be measured intermittently or at low speed.



Version Q/QA



Version H/HA



Version R

Technical Data

Mechanical Basic Data

Measuring range	N·m	±2 ... 1 000
Rated torque M_{nom}	N·m	2 ... 1 000
Overload capacity		
Service torque		1,5 x M_{nom}
Limiting torque		1,5 x M_{nom}
Rotational angle measurement (Version QA)	pulses/ revolut.	2x360, 90° displaced, TTL
Nominal speed	1/min	3 000
Housing material		Anodized aluminum
Protection class		IP40

General Electrical Specifications

Accuracy class		0,2
Linearity error including hysteresis	% FSO	<±0,2

Relative hysteresis error	% FSO	<±0,1
Temp. influence on the zero point	% FSO/°C	<±0,015
Temp. influence on the nominal value	% FSO/°C	<±0,015
Control signal	%	100±0,2
Bridge resist., strain gage full bridge	Ω	350 nominal
Rated value		
<6 N·m rated torque	mV/V	1
≥6 N·m rated torque	mV/V	2
Operating temperature range (Rated temperature range)	°C	5 ... 50
Service temperature range	°C	-10 ... 70
Storage temperature range	°C	-25 ... 80
Electrical connection		6-pin or 12-pin built-in connector
Supply voltage strain gage	VDC/VAC	max. 12
Supply voltage angle	VDC/mA	5/35


Dimensions



Torque sensor with standard square socket connection

Version Q

- With rotating shaft
- Drive - inside square socket
- Output - external square socket



Dimensions Version Q

Threads for mounting: M4, 6 mm depth

Type	Measuring range N·m	Socket size Vk	A	B	C	D	E	F	G	H	I	øL	øN	O	Axial force N max.
4501A6Q	6	1/4"	75	28	52	58	14	8,5	8	5	11	13	10	37	150
4501A12Q	12	1/4"	75	28	52	58	14	8,5	8	5	11	13	10	37	150
4501A25Q	25	3/8"	74,5	38	58	44	19	18	—	6	22	25	19	23	550
4501A63Q	63	3/8"	74,5	38	58	44	19	18	—	6	22	25	19	23	1 000
4501A160Q	160	1/2"	79	38	58	44	19	22,5	—	6	22	25	19	23	1 800
4501A500Q	500	3/4"	97	58	76	50	29	30	—	5	25	40	30	27	4 000
4501A1KQ	1 000	1"	112	73	90	57	36,5	34,5	—	5	28,5	50	40	28,5	6 000

Axial force values apply for unsecured housing

Dimensions




Torque sensor with standard square socket connection

Version QA

- With rotating shaft
- Drive - inside square socket
- Output - external square socket
- Rotational angle measurement

(M) = Measuring end



Dimensions Version QA (with rotational angle measurement)

Type	Measuring range N·m	Socket size V _k	A	B	C	D	E	F	G	H	I	K	øL	øN	O	Axial force N max.
4501A6QA	6	1/4"	75	28	52	58	14	8,5	8	5	11	–	13	10	37	150
4501A12QA	12	1/4"	75	28	52	58	14	8,5	8	5	11	–	13	10	37	150
4501A25QA	25	3/8"	101	38	58	59	19	21,5	14	5	12	35	25	17	38	550
4501A63QA	63	3/8"	101	38	58	59	19	21,5	14	5	12	35	25	17	38	1 000
4501A160QA	160	1/2"	106	38	58	59	19	26	14	5	12	35	25	17	38	1 800
4501A500QA	500	3/4"	135	58	76	64	29	40	30	5	14	36	40	30	40	4 000
4501A1KQA	1 000	1"	177	73	90	73	36,5	57,5	45	5	14	45	50	40	44	6 000


Axial force values apply for unsecured housing

Dimensions



Torque sensor with standard 1/4" hex
DIN3126 form E/F, Version H

- With rotating shaft
- Drive - external hex
- Output - inside hex
- Rotational angle measurement (HA)
- Quick action chuck



Dimensions Version H or HA (Rotational angle measurement)

Threads for mounting: 6x M4, 6 mm depth

Type	Measuring range N·m	Nominal value mV/V	A	B	C	D	E	F	Axial force N max.
4501A2H, ...HA	2	1	101	28	52	58	14	28	20
4501A6H, ...HA	6	2	101	28	52	58	14	28	50
4501A12H, ...HA	12	2	101	28	52	58	14	28	50
4501A20H, ...HA	20	2	101	28	52	58	14	28	150


Axial force values apply for unsecured housing

Dimensions



Torque sensor with feather keyways (2x180°)
DIN 6885, Version R

- With rotating shaft



Dimensions Version R


Threads for mounting: 3x M4, 5 mm depth

Type	Measuring range N·m	Nominal value mV/V	A	B	C	D	E	F	G	H	I	K	L	øN g6	Axial force N max.
4501A10R	10	2	108	38	58	44	19	30	19	6	22	53	32	19	150
4501A20R	20	2	108	38	58	44	19	30	19	6	22	53	32	19	550
4501A50R	50	2	108	38	58	44	19	30	19	6	22	53	32	19	1 000
4501A100R	100	2	108	38	58	44	19	30	19	6	22	53	32	19	1 800
4501A200R	200	2	182	73	90	57	36,5	60	36,5	5	28,5	90,5	63	38	4 000
4501A500R	500	2	182	73	90	57	36,5	60	36,5	5	28,5	90,5	63	38	6 000
4501A1KR	1 000	2	182	73	90	57	36,5	60	36,5	5	28,5	90,5	63	38	6 000

Axial force values apply for unsecured housing

Electrical Connections


Pin Allocation of the 12 Pin Built-in Connector for Version QA

	Function	PIN		Description
	Torque strain gage measuring bridge	A	-U _E	Supply–
		B	+U _E	Supply+
		C	+U _A	Measuring signal output+
		D	-U _A	Measuring signal output–
	Angle of rotation sensor Supply	E	GND	Ground relating to +U _B
	Angle of rotation pulses	F	+U _B	5 VDC ±10 %
		G	Track A	Open collector output
		H	Track B	Internal 1 kΩ resistance to 5 VDC (pull up), TTL-level
		J	DGND	As Track A, 90° displaced
	100 % control input	K	Control	Ground relating to angle pulses
				Off: not connected
				On: connected with PIN A
	Shield	M		In sensor connected to housing

On request available with "Bendix" connector

*At clockwise rotation (view on drive end)

Pin Allocation of the 6 Pin Built-in Connector for Version Q, R, H

	Function	PIN		Description
	Torque strain gage measuring bridge	1	-U _E	Supply–
		2	+U _E	Supply+
		4	+U _A	Measuring signal output+
		5	-U _A	Measuring signal output–
	100 % control input	6	Control	Off: not connected
				On: connected with PIN 1
	Shield	3		In sensor connected to housing

On request available with "Bendix" connector

Included Accessories

- None

Optional Accessories

- | | |
|--|---------------|
| • Female connector with solder eye 6 pin | KSM000822 |
| • Female connector with solder eye 12 pin | KSM000703 |
| • Connection cable, 5 m, 6 pin | KSM071860-5 |
| • Connection cable, 5 m, 12 pin | KSM170690-5 |
| • Connection cable, 5 m, 6 pin – open ends | KSM103820-5 |
| • Connection cable, 5 m, 12 pin – open ends | KSM183150-5 |
| • Amplifier for strain gage sensors | 4701A... |
| • ControlMonitor CoMo Torque
Evaluation instrument for torque sensors | 4700A... |
| • Connection cable,
2,5 m, 6 pin – CoMo Torque | KSM185350-2,5 |
| • Connection cable, 2,5 m,
12 pin – CoMo Torque | KSM185370-2,5 |

Application Example

Power tool control



Ordering Key

Type 4501A ☐ ☐

Measuring Ranges in N·m/

Available Versions

2	–	–	H	HA	–	2
6	Q	QA	H	HA	–	6
10	–	–	–	–	R	10
12	Q	QA	H	HA	–	12
20	–	–	H	HA	R	20
25	Q	QA	–	–	–	25
50	–	–	–	–	R	50
63	Q	QA	–	–	–	63
100	–	–	–	–	R	100
160	Q	QA	–	–	–	160
200	–	–	–	–	R	200
500	Q	QA	–	–	R	500
1 000	Q	QA	–	–	R	1K

Versions

(Note Dependence with Measuring Range)

Square socket	Q
Square socket with rotational angle meas.	QA
1/4" hex	H
1/4" hex with rotational angle meas.	HA
Feather keyways	R

Order example:

Type 4501A12QA

Torque sensor: rated torque **12 N·m**, Version **QA**: square socket with Rotational angle measurement